

OUT54047

HFS \_\_\_\_\_

CJS \_\_\_\_\_

1964 SEP 9 00 01 Z

PJS \_\_\_\_\_

ACH \_\_\_\_\_

Grace (File)

*Multi*  
P 082301Z  
FM NPIC WASHDC  
TO RUCSBR/SAC OFFUTT AFB OMAHA NEB  
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
RUCVAA/2D RTS BARKSDALE AFB LA  
RUEAHQ/DIA WASHDC  
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD  
RUEPIA/CIA WASHDC  
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF  
RUWGAA/2AF BARKSDALE AFB LA  
BT  
S E C R E T CITE NPIC 2879.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B-101 WAS EMPLOYED IN MISSION 3943 FLOWN 7 SEPTEMBER 1964. PROCESSING WAS ACCOMPLISHED AT BARKSDALE AFB.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: BOTH EDGES CONTAIN MINOR EDGE STATIC DISCHARGES AND OR ROLLER INDUCED STATIC TRACES THROUGHOUT THE FIRST HALF OF THE PAYLOAD. FRAMES 000-299 CONTAIN A ROW OF MINUS DENSITY SPOTS PARALLEL TO AND 1.45" FROM THE OUTBOARD EDGE OF THE FILM. THE SPACING BETWEEN SPOTS IS 2.30". FINE PLUS DENSITY STREAKS ARE PRESENT INTERMITTENTLY.

C. 9L SIDE: MINOR EDGE STATIC DISCHARGES OCCUR INTERMITTENTLY ON BOTH EDGES. A CONTINUOUS, FINE MINUS DENSITY STREAK RUNS PARALLEL TO AND 4.90" FROM THE INBOARD EDGE. MINOR PROCESSING STREAKS ARE PRESENT INTERMITTENTLY ON THE INBOARD EDGE. EXCESSIVE HANDLING MARKS ARE PRESENT AT A NUMBER OF CUTS.

D. BOTH SIDES: IMAGE MOTION IS EVIDENT IN APPROXIMATELY 20

-2-

FRAMES. BOTH SIDES CONTAIN TITLED FRAMES 0000-2376.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING FAULTS.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUD COVER OBSCURES 15 PERCENT OF THE GROUND IMAGERY.

S E C R E T

/END OF MESSAGE/